




[virtual]

## HIGH PERFORMANCE ENGINEERING SOLUTIONS 2021

28<sup>th</sup> September – 1<sup>st</sup> October

### PTC Creo CAM

28 settembre 2021



#### Agenda

<b>14:00 - 18:00</b>	Intro Creating Manufacturing Models Configuring Operations Reference Models and Workpiece models Create and configure Work Center Tools and parameters 5 axis toolpath examples: <ul style="list-style-type: none"> <li>- Define conventional and cutline milling</li> <li>- Define swarf milling</li> <li>- 5 axis holmaking</li> <li>- 3+2 axis HSM roughing</li> <li>- 5 axis HSM roughing</li> <li>- Auto Deburring</li> </ul>